

	Type	L #	Hits	Search Text	DBs	Time Stamp	Comments
11	BRS	L12	14	(combin\$6 near2 control\$4 near2 signal\$1) with (weight\$3 near3 factor\$1 or weight\$3 near3 coefficient\$1 or weight\$3 near3 tap\$3 or tap\$1 near2 coefficient\$1)	US- PGPUB ; USPAT ; EPO; JPO	2006/03/29 13:08	
12	BRS	L15	22	(combin\$6 near2 control\$4 near2 signal\$1) same (weight\$3 near3 factor\$1 or weight\$3 near3 coefficient\$1 or weight\$3 near3 tap\$3 or tap\$1 near2 coefficient\$1)	US- PGPUB ; USPAT ; EPO; JPO	2006/03/29 13:05	
13	BRS	L16	8	15 not 12	US- PGPUB ; USPAT ; EPO; JPO	2006/03/29 13:05	
14	BRS	L17	52	(combin\$6 near2 control\$4 near2 signal\$1) near4 (weight\$3)	US- PGPUB ; USPAT ; EPO; JPO	2006/03/29 13:09	
15	BRS	L18	24	17 and (phase near3 shift\$3 or shift\$3 near3 register\$1 or cod\$3 near2 phase\$1)	US- PGPUB ; USPAT ; EPO; JPO	2006/03/29 13:19	
16	BRS	L19	28	17 not 18	US- PGPUB ; USPAT ; EPO; JPO	2006/03/29 13:19	

	Error Definition	Err ors
11		
12		
13		
14		
15		
16		

	Type	L #	Hits	Search Text	DBs	Time Stamp	Comments
17	BRS	L20	23	19 not 15	US- PGPUB ; USPAT ; EPO; JPO	2006/03/2 9 13:19	

	Error Definition	Err ors
17		